




Important

- : Always shake bottles very well!
- : Always use clean polishing pads!

UHS Clear Coat 93 2:1 Excellent (9310)

HS Clear Coat 92 2:1 Plus (9210)

Kristal TimeClear 4:1: (9410)

				PARTNR.	Important:
Step 1 	Remove dust particles, sags or paint imperfections	Trizact Micro Polishing disk on red sanding block P2000/P2500 WOD using: WOD foam rubber block WOD Rubber scraper Sand again with 3M Trizact P3000 (using damp)		50079/13441 09546/02045 05526 05517 50414 / 50415	Works very local. Remove sanded particles from surface and/or sanding material
	Remove and reduce spray structure (orange peel) and sand larger surfaces	Eccentrically rotating machine Soft interface pad 260L P1500 when paint is old Sand again with 3M Trizact P3000 (using damp)		50396 / 50397 62001 50414 / 50415	Dust extraction very important. Regularly remove dry sanding dust from sanding disk through foam or cloth/paper
	Remove paint spray and pollution by industrial emissions	Cleaning clay		38070	
Step 2 	Compounding/polishing	Fast-Cut Compound (green cap) Sponge (green) 75/150 mm Remove excess with cloth		50417 50499/50487	<i>Shake well before use!</i> Little compound works best Move machine actively. Rinse sponge/coat after use
	Check result + remove compound	Solvent/Finish Control Spray Rub with polishing cloth		55535	When spot is still visible, compound again with 50417
Step 3 	Gloss result	Gloss polish (yellow cap) Waffel sponge (yellow) 76/150 mm Remove residue with polishing cloth		80349 50536/50488	<i>Schake well before use!</i> Little compound works best. Prevent "running dry". Moving machine prevents building up heat